

建造業安全周2019 - 研討會

許海航工程師 總助理秘書長 (工務) 5

2019年5月20日





上一個世紀...









大魔術師?

輕功水上漂?









19 May 2019 News








Fatal incidents in late 2018/early 2019

日期	事件
6/12/2018	沙頭角地盤貨車溜後 1工人慘遭撞斃
13/12/2018	深水埗棚架工人高處墮下 送院搶救不治
27/12/2018	首日開工遇意外 油美苑搭棚工人墮樓亡
9/1/2019	鑽石山悅庭軒男裝修工 26樓棚架墮下送院亡
12/1/2019	工人昂船洲軍營鋪水泥 失足10米高墮斃
26/1/2019	長沙灣伸縮篷支架擊中 中年技工人仰梯翻墮樓亡
11/2/2019	【罕見意外】大埔工程車升降台疑撞架空電纜 街燈清潔工觸電慘死
22/2/2019	太古坊貨車塌兩噸重玻璃 倉務員助「睇位」慘遭壓斃
25/2/2019	新田車場輪胎充氣時爆開 工人遭氣流擊中不治
2/3/2019	觀塘地盤墮木方擊斃泥水工 勞工處發「暫時停工通知書」
5/3/2019	元朗及荃灣發生工業意外 3工人平台墮下受傷 (1個工人期後不治)
11/3/2019	【奪命工傷】荃灣冷氣機雪種泵爆炸 29歲技工搶救一日不治
3/4/2019	【致命意外】屯門內河碼頭 女工遭貨櫃起卸機輾斃
16/4/2019	【科學園工業意外】昨遭木板壓中 泰籍工人今不治
18/4/2019	青衣運沙船工人墮船艙 重傷不治

Accident Rates



Overall Industrial Accidents @17.2/1000 workers

50


40

30


20

10

Construction Accidents @32.9/1000 workers



No. of fatalities



Accident and Fatality Rates

days.




United Kingdom

9

Collaboration with Stakeholders



Actions taken by Government



Summary of Major Actions taken


Government	rnment Contractors Consultants		Workers			
Considerate Construction Safety Award Scheme (1995)						
Pay for Safety (1995)	Site Safety	Caring and safety alert (2012)				
Caring Visit (2012)	Caring Visit (2012) Tendering (1998, Design for Safety 2002, 2014, 2017) (2006, 2016)		Builder's lift (2014)			
Construction Safety Week (2012)						
Safety audit (2013, 2018)	Score Card (2000, 2019)	Training & Qualification (2001, 2017)	Hot weather (2018)			
Pay for Safety Performance Merit Scheme (2013)	Panel of Enquiry (2009, 2017)		BAP (2018)			

Pay for Safety

Pay for Safety Scheme (1.2% of contract sum max.)

Appendix I(a) - Sample Bill of Quantities for works contracts included in PFSS Based on \$ 200M contract value or below over a construction period of 2 years

Item No.	Description	Quantity	Unit	Suggested Amount (% of contract value*)
A	Provide Safety Officer	48	nr-mth	0.216%
В	Attend Site Safety Management Committee	24	mth	0.050%
C	Attend Site Safety Committee	24	mth	0.050%
D	Arrange and attend weekly safety walk	104	nr	0.150%
E	Provide safety training in the form of safety training for specified trade workers (i) One day course (ii) Half day revalidation course	33	nr nr	0.011%* 0.007%*
F	Provide safety training in the form of site specific induction training	30	mth	0.051%
G	Provide safety training in the form of toolbox talks	30	mth	0.102%
Н	Provisional Sum Participate in safety promotional campaign as instructed by the Architect/Engineer	-	sum	0.030%
I	Arrange and hold Pre-work Activities of Site Safety Cycle	30	mth	0.480%
J	Prevention of heat stroke at work in a hot environment	10	mth	0.050%
	Total to Collection Sheet			1.2%



Pay for Safety Performance Merit Scheme

Pay for Safety Performance Merit Scheme (1.7% of contract sum)

MEMO Secretary for Development Distribution Ref (02LSW-01-1) in DEVB(W) 516/70/03 (Attn : 3509 8277 Tel. No. Your Ref. Fax No. 2524 9308 dated clwong@devb.gov.hk Fax No. Email 22 November 2013 Total Pages 3 + Encl. Date

Pay for Safety Performance Merit Scheme

This memo promulgates the Pay for Safety Performance Merit System (PFSPMS) in public works contracts as an extension to the existing Pay for Safety and

香港特別行政區政府 The Government of the Hong Kong Special Administrative Region

政府總部 環境運輸及工務局 香港花園道美利大廈



Environment, Transport and Works Bureau Government Secretariat Muray Building, Garden Road, Hong Kong

Ref. : ETWB(W) 517/91/01

Group: 2, 5, 7, 8, 12

29 December 2005

Environment, Transport and Works Bureau Technical Circular (Works) No. 19/2005

Environmental Management on Construction Sites

Annex E - Part II (A)

Sample Schedule of Performance-tied Payment Items of the PFSPMS

(Based on \$200M estimated contract value, excluding the Contingency Sum and any sum allowed for fluctuations, for a contract period of 24 months)

Schedule of Performance-tied Payment Items of the PFSPMS

Item no.	Description of Payment items on performance indicators	Quantity	Unit	Rate (\$)	Amount (\$)	[Assigned % on capped amounts]
1.	No reportable accidents in a month	34^	month	12,000	408,000*	[12%]
2.	No notice of safety or environmental prosecution received in a month	34^	month	12,000	408,000*	[12%]
3.	Safety training (Silver Card) for specified trade workers compliance per month Payment to be made if: no. of Silver Card compliance/ total no. of workers requiring Silver Card > 90% on a date specified by the Architect/Engineer/Supervising Officer during the month	34^	month	6,000	204,000*	[6%]
4.	Half-yearly review of safety performance – notices from Labour Department (LD)					
	Payment to be made if there is:- No Part I Inspection Notice ^(note 2) from LD; Not more than 5 Part II Inspection Notice ^(note 2) from LD; and No Improvement Notice or Suspension Notice from LD in half year	5.6^	Half-year	73,000	408,800*	[12%]
5.	12-month rolling accident frequency rate for reportable accidents below 0.25 per 100,000 man-hours worked	23^^	12-month rolling period	27,000	621,000*	[18%]
6.	Yearly review of safety performance - no fatal accident in a year	2.8^	year	220,00	616,000*	[18%]
7.	Achievement in safety campaigns organized by Development Bureau (i) Considerate Contractors Site Award (CCSA*)					
	(a) Obtaining gold award	2	nr	120,000	240,000*	[7% or \$0.36M whichever is the lower]

Application of Innovative Technology

- Technology for construction
 - Steel prefabrication yards
 - MiC





- Safety devices
 - Remote sensing (e.g. RFID)
 - CCTV
 - Smart IOT helmet
- To provide incentives in Safety
 Score Card






Promotion of Innovative Devices









 Three different application methods to ensure the worker's safety belt is properly installed









Panel of Enquiry

香港特別行政區政府

The Government of the Hong Kong Special Administrative Region

政府總部

發展局

工務科

香港花園道美利大廈

Works Branch
Development Bureau
Government Secretariat
Murray Building, Garden Road,
Hong Kong

Ref. : DEVB(W) 516/14/02

Group: 2, 8, 12


13 March 2009

Development Bureau


Technical Circular (Works) No. 3/2009

Regulating Action against Contractors for Occurrence of a Serious Incident or Conviction for Site Safety or Environmental Offences

Design for Safety








Construction Design and Management (CDM) 2006






Design for Safety 2016


Schematic Design of Temporary Works

Conduct pilot trials to improve the constructability of the permanent works through early identification of the potential safety hazards









Safety Role of RSS

Enhanced Role of Professional Resident Site Staff (RSS) in Site Safety of Mega Works Projects

This memo is to promulgate the enhanced role of professional grade RSS in the safety supervision of mega works projects.

- 2. The occurrence of a series of serious accidents in large-scale public works projects in late 2012 received serious attention of DEVB and the Labour Department. A meeting was held among DEVB, Works Departments and Labour Department in February 2013 and it was agreed, among other things, that the professional grade RSS in "mega works projects" could play a more proactive role to ensure the safe systems of work on sites. It was agreed that the role of professional grade resident site staff (RSS) in day-to-day supervision of "mega works projects" could be enhanced by requiring: -
 - (a) dedicated professional grade RSS to participate in the weekly safety walk;
 - (b) dedicated professional grade RSS to carry out spot checking of high risk construction activities; and
 - (c) dedicated professional grade RSS to carry out daily review with the Contractor of all high risk activities.

Surprise Audits

- Conducted surprise audits by Independent Audit Team of works departments for contracts with
 - poor safety performance
 - high accident rate (> 0.5 per 100,000 man-hours)
 - suspension notice(s) issued from Labour Dept
 - severe accidents / dangerous occurrences




Monitoring of Accidents in PWPs






Behaviour Advancement Programme






Conduct wider trials for improvement of workers' behaviour



Welfare for Workers


Implementation of measures for preventing heat stroke at work under hot environment

Item No.	Description	Quantity	Unit	Suggested Amount (% of contract value [#])
A	Provide Safety Officer	48	nr-mth	0.216%
В	Attend Site Safety Management Committee	24	mth	0.050%
С	Attend Site Safety Committee	24	mth	0.050%
D	Arrange and attend weekly safety walk	104	nr	0.150%
Е	Provide safety training in the form of safety training for specified trade workers (i) One day course	33	nr	0.011%*
	(ii) Half day revalidation course	40	nr	0.007%*
F	Provide safety training in the form of site specific induction training	30	mth	0.051%
G	Provide safety training in the form of toolbox talks	30	mth	0.102%
Н	Provisional Sum Participate in safety promotional campaign as instructed by the Architect/Engineer	-	sum	0.030%
I	Arrange and hold Pre-work Activities of Site Safety Cycle	30	mth	0.480%
J	Prevention of heat stroke at work in a hot environment	10	mth	0.050%
	Total to Collection Sheet		1.2%	



Welfare for Workers

Provisions of builder lifts for high rise buildings > 30m or 8 storeys for better access and egress of workers





The requirements for builders' lifts will be incorporated into the Tender Documents, wherever applicable, as follows –

(i) It is required that for the construction of a high-rise building over 30m high or 8 storeys measured from the main access level up to the main roof, whichever is lower, a Builder's lift will be installed in order to provide a better means of access and egress for workers and site supervisory staff. It will also improve the safety and health of the working environment in building construction sites and productivity of the workers.

Responsibility & Accountability

11/4/2019 項目經理、地盤總管、工人及地盤安全主任因違犯 安全法例被判罰款 一名項目經理、一名地盤總管、一名工人及一名地盤安全主任因達犯《工廠及工業經營條例》的規定,被勞工處 檢控,今日(四月十一日)在西九龍裁判法院分別被判罰款五千元、五千元、五千元及八千元。

案情涉及二〇一七年十月二十日在東涌一個建築地盤發生的一宗致命意外的調查。在調查過程中,該地盤項目經理、地盤總管及工人沒有依從勞工處職業安全主任就該意外調查所作出的要求,接受訊問並簽署聲明。另外,該地盤安全主任妨礙及拖延職業安全主任行使條例所接予他們的權力。

勞工處發言人說:「我們絕不容忍任何不遵從職業安全主任根據《工廠及工業經營條例》規定所作出的要求,或 妨礙或拖延職業安全主任行使條例所授予他的權力的違法行為,並會竭盡所能將違例者繩之於法。|

完

上水名都巴黎閣去年發生的致命升降機意外,負責該升降機的73歲註冊電梯工程師吳茂 盛承認「沒有確保升降機工程妥善進行」的控罪,在粉嶺裁判法院被判罰款4萬元。他在 案發後因壓力而辭去逾40年的工程師一職。

去年5月11日,64歲女住客郭妙英在7樓進入升降機時,升降機門突然關上將女事主夾著 失控上升,女事主直墮槽底喪命。

涉案的升降機保養承辦商耀天工程有限公司及公司總經理劉慶秋,早前已承認「沒有確保升降機工程妥善進行」,以及「外判升降機保養工程前沒通知機電工程署署長」等控罪,分別被判罰款63000元及33000元。

26/4/2019 上水名都致命升 降機意外 電梯工程師認罪判 罰款4萬元

2/5/2019 躉船浮標燒焊爆炸 巴籍工人亡 家屬向承建商 索償 「中環及灣仔繞道——北角段隧道及東區走廊連接路工程」於3年前動工期間,一個薑船浮標在燒焊期間發生爆炸,導致一名38歲巴籍工人死亡和另一名工人受傷。死者家曆前日(4月30日)就事件入稟高等法院向承建商家價。

兩名原告分別是死者Mamraiz Khan的代表,及死者的家屬代表 Musrat;兩名被告分別是俊和 - 中國中鐵 - 中鐵大橋局聯營公司, 及中國鐵路工程(香港)有限公司。

入棄狀指稱,死者於2016年5月4日在東區走廊北角段對開的薑船浮標工作時,題上致命意外死亡,事件是因兩名被告疏忽和違反僱傭合約所致,兩名原告因此向兩名被告素償。







Tragedies...

defendants, 57 summonses

- ➤ 16 summonses each to 3 partners of main contractor
- 2 summonses to consultants
- 2 summonses each to 2 involved subcontractors
- 1 summons to Foreman on site
- 1 summons to General Site Manager
- 1 summons to Senior Engineer of consultants

Responsibility & Accountability



葛麦斯驾车43载,不仅从未发生过交通事故,甚至连一次违章纪录都没有,因此在他退休前,交通部决定颁发一枚"优秀模范驾驶奖章"给他。颁奖当天,记者问葛麦斯要如何才能做到平安驾车呢?葛麦斯回答道:"其实开车时,我都由家人陪着啊!不过乘客看不到我的家人,因为他们都在我的心里。"葛麦斯笑着说:"想想你的妻子正等着你吃晚餐;你还要陪孩子上学;年迈的父母正是需要你照顾的时候……你就会小心驾驶。"原来,葛麦斯的秘诀,就是时时刻刻把对家人的爱放在心中。



Thank Your FOR WORKING SAFELY

Zero意外 A C C I D E N T

地盤零意外。關懷建未來

Zero Accident, we Build, we Care